

sømcasa



B*1



C*3



D*3



E*6




F*6



G*12




H*6


$$I * 1$$


Do not tight any screw too much until all the screws have been connected.

A technical drawing of a mechanical assembly. It features a circular base plate with several small circular features, possibly holes or rivets. Two long, angled arms or levers are mounted on the base. One arm is positioned higher than the other, and they appear to be connected to a central pivot point. A label 'G' with an arrow points to a specific feature on the base plate.



A simple line drawing of a round table with three legs. The table has a flat, circular top and three straight, slightly tapered legs. The drawing is minimalist, using only black outlines on a white background.

